

NOTES:

1. INNER BARE WIRES ARE CUT OFF INSIDE THE TRANSDUCER.
2. VIOLET WIRE IS CUT OFF ON BOTH ENDS.
3. OLD PCBA PART NUMBER IN BRACKETS.

